



CENTURY BLVD





CENTURY BOULEVARD

PRAIRIE AVENUE


DOTY AVENUE

102ND STREET

102ND STREET

- LEGEND:**
-  CHAIN LINK FENCE
 -  CMU WALL
 -  WROUGHT IRON FENCE W/PILASTERS
 -  BUILDING EDGE

NOTE:
ALL DIMENSIONS ARE APPROXIMATED BASED ON
AERIAL IMAGES AND SITE OBSERVATIONS.





 <p>D & D ENGINEERING, INC. 8901 S. LA CIENEGA BLVD, SUITE 106 INGLEWOOD, CA 90301 Phone: 424-393-4122</p>	PROJECT CONDOR	SCALE: AS SHOWN
	PERIMETER CONDITIONS EXHIBIT	DATE: 2017/10/24
		SHT NO.: 01 OF 01


PHOTO KEY MAP



2014

100 CENTURY

BLVD 88



LEGEND:

PHOTO AREA AND DIRECTION

ALL 900 SERIES PARCELS ON THIS PAGE ARE ASSESSED TO THE CITY OF INGLEWOOD, AS SUCCESSOR AGENCY FOR THE FORMER INGLEWOOD REDEVELOPMENT AGENCY, UNLESS OTHERWISE NOTED



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILLASTERS ON

1



PICTURE NOTES:

SOUTHEAST VIEW FROM MIDDLE OF
PARCEL ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILLASTERS ON

2



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHWEST CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK FENCE, CMU WALLS AND A WROUGHT IRON FENCE WITH PILLASTERS ON

3



PICTURE NOTES:

NORTHBOUND VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILLASTERS ON

4



PICTURE NOTES:

NORTHWEST VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILLASTERS ON

5



PICTURE NOTES:

WESTBOUND VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILLASTERS ON

6




PICTURE NOTES:

NORTHBOUND VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILLASTERS ON

7



PICTURE NOTES:

EASTBOUND VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILLASTERS ON

PHOTO KEY MAP


2014

100 CENTURY

BLVD 100



MAPPING AND GIS SERVICES SCALE 1" = 80'



LEGEND:





PHOTO AREA AND DIRECTION



ALL 900 SERIES PARCELS ON THIS PAGE ARE ASSESSED TO THE CITY OF INGLEWOOD, AS SUCCESSOR AGENCY FOR THE FORMER INGLEWOOD REDEVELOPMENT AGENCY, UNLESS OTHERWISE NOTED



PICTURE NOTES:

WESTBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG CENTURY

SITE SURREOUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

9



PICTURE NOTES:

EASTBOUND VIEW FROM NORTHWEST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

10



PICTURE NOTES:

WESTBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

11



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

12



PICTURE NOTES:

WESTBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

13



PICTURE NOTES:

WESTBOUND VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

14



PICTURE NOTES:

WESTBOUND VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

15



PICTURE NOTES:

NORTHBOUND VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

16



PICTURE NOTES:

NORTHBOUND VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

17



PICTURE NOTES:

EASTBOND VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURREOUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

18



PICTURE NOTES:

EASTBOUND VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURREOUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS



PICTURE NOTES:


NORTHBOUND VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 102ND


SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

20

- REVISED
- 10-3-56
 - 7-10-58
 - 11-19-58
 - 4-14-60
 - 9-19-60
 - 8-31-61
 - 12-6-61
 - 3-30-62
 - 750113002
 - 770808806
 - 780425053
 - 840717402-85
 - 841212413-85
 - 850213004-85
 - 850530810-86
 - 851216608-86
 - 870408601-87
 - 90041002004001-09
 - 94040412001001-09
 - 96100402006001-09
 - 1998120908004001-09
 - 1999112408009001-09
 - 2000011009007001-09
 - 2000013104004001-09
 - 2000061502014001-09
 - 20000627
 - 2001022109004001-09
 - 2002043010011001-09
 - 2002080508009001-09

PHOTO KEY MAP



LEGEND:
 PHOTO AREA AND DIRECTION

PARCEL MAP

P.M. 226-86

All 900 series parcels on this page are assessed to the Inglewood Redevelopment Agency, unless otherwise noted.

LOCKHAVEN TRACT

PARCEL MAP
P.M. 51-66

M.B. 17-87

CODE
4595

FOR PREV. ASSM'T. SEE: 1532-1
4032-2



PICTURE NOTES:

WESTBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

22



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHWEST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

23



PICTURE NOTES:

WESTBOUND VIEW FROM MIDDLE OF
PARCEL ON NORTH END, ALONG
CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

24



PICTURE NOTES:

SOUTHWESTBOUND VIEW FROM MIDDLE
PARCEL ON NORTH END, ALONG
CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

25



PICTURE NOTES:

SOUTHEASTBOUND VIEW FROM MIDDLE OF PARCLE ON NORTH END, ALONG CENTURY

SITE SURREOUNDED BY CHAIN LINK FENCE, CMU WALLS AND A WROUGHT IRON FENCE WITH PILASTERS

26



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHWEST
CORNER OF PARCEL, ALONG CENTURY

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

27



PICTURE NOTES:

NORTHBOUND VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

28



PICTURE NOTES:

WESTBOUND VIEW FROM SOUTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS



PICTURE NOTES:

NORTHWESTBOUND VIEW FROM SOUTH
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

30



PICTURE NOTES:

NORTHEAST VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 102ND


SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

31

PHOTO KEY MAP

11-16-59
9-19-60
2-1-63
87112106001001
90081614003001-09
97051507003001-09
1999120104009001-09
2000061502015701-09
321112
2003031906007001-09
2004091003001001-09
2005063006009001-09
2007121011005001-09
2008122407005001-09

2009



LOCKHAVEN TRACT

M.B. 17-87

LEGEND:




PHOTO AREA AND DIRECTION

CODE
13267



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

32



PICTURE NOTES:

SOUTHEASTBOUND VIEW FROM
NORTHWEST CORNER OF PARCEL, ALONG
102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS

33



PICTURE NOTES:

SOUTHBOUND VIEW FROM MIDDLE OF
PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS AND A WROUGHT
IRON FENCE WITH PILASTERS



PICTURE NOTES:

WESTBOUND VIEW FROM NORTHWEST CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK FENCE, CMU WALLS, BUILDINGS

35



PICTURE NOTES:

SOUTHWESTBOUND VIEW FROM
NORTHWEST CORNER OF PARCEL, ALONG
102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

36



PICTURE NOTES:

WESTBOUND VIEW FROM NORTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

37

PHOTO KEY MAP



MAPPING AND GIS SERVICES
SCALE 1" = 80'

2015


BK 4034

103RD ST

AVE 100

C S B-142B-3

PRAIRIE 100



LEGEND:




PHOTO AREA AND DIRECTION



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

38



PICTURE NOTES:

WESTBOUND VIEW FROM NORTHEAST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

39



PICTURE NOTES:

SOUTHEASTBOUND VIEW FROM MIDDLE
OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

40



PICTURE NOTES:

SOUTHEASTBOUND VIEW FROM MIDDLE
OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

41



PICTURE NOTES:

SOUTHBOUND VIEW FROM NORTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

42

PHOTO KEY MAP



LEGEND:




PHOTO AREA AND DIRECTION



PICTURE NOTES:

NORTHBOUND VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

43



PICTURE NOTES:

WESTBOUND VIEW FROM NORTHWEST
CORNER OF PARCEL, ALONG 102ND

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

44




PICTURE NOTES:

SOUTHEASTBOUND VIEW FROM
NORTHWEST CORNER OF PARCEL, ALONG
101ST

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

45

PHOTO KEY MAP



LEGEND:



PHOTO AREA AND DIRECTION



PICTURE NOTES:

NORTHBOUND VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 101ST

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

46



PICTURE NOTES:

EASTBOUND VIEW FROM SOUTHWEST
CORNER OF PARCEL, ALONG 101ST

SITE SURROUNDED BY CHAIN LINK
FENCE, CMU WALLS, BUILDINGS

47