

Message

---

**From:** Dennis Kanuk [dennis@mcadvise.com]  
**Sent:** 5/15/2019 9:16:13 AM  
**To:** Addie Farrell [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=cc6bb601520a4f9690ae254948d782f5-Addie Farre]  
**CC:** Brian Boxer [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=a4f8c4ab743d4d5194aa8b3d8c519c29-Brian Boxer]; Christina Erwin [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=4dddbff2e8414460abdcaefc2d500dd-Christina E]; Mindala Wilcox [mwilcox@cityofinglewood.org]  
**Subject:** IBEC: Updated fire protection and reclaimed water diagrams  
**Attachments:** IBEC Reclaimed Water Diagram 5.14.19.pdf; IBEC Fire Protection Diagram 5.14.19.pdf

Hi, Addie,

I confirmed with D&D Engineering that pipe diameters for the lines shown on the updated wet utility diagrams are correct per the Golden State Water Company map book.

As I mentioned, we did receive very minor updates to the IBEC fire protection diagram and reclaimed water diagram (attached), with changes as follows:

Reclaimed water – practice & training facility label/size changed to match other diagrams

Fire protection – update to legend for removed lines

Dennis Kanuk

**MONTGOMERY CLARK ADVISORS**

10877 Wilshire Blvd. Ste. 1102

Los Angeles, CA 90024

E-Mail: [Dennis@mcadvise.com](mailto:Dennis@mcadvise.com)

Office: (310) 443-7711

Mobile: (213) 309-5652